


Odometer/Tripmeter Display

The display (1) shows two functions: odometer and two tripmeters.

Push the button (2) to select the “ODO” and “TRIP1”, “TRIP2” mode.

To reset the tripmeter, push and hold the button (2) when the display is in the “TRIP1” or “TRIP2” mode.




- (1) Odometer/Tripmeter display
(2) Odometer/Tripmeter select and reset button


Odometer



Tripmeter 1



Tripmeter 2



Tripmeter reset

