

Changing down the gears

Changing down gears provides greater acceleration in situation such as overtaking. Avoid changing down at high speed, which can damage both the engine and the transmission by running the engine at excessively high rpm.

The table shows the maximum speed for each shift down.

	Maximum Speed
6 th - 5 th	140 km/h & below
5 th - 4 th	120 km/h & below
4 th - 3 rd	80 km/h & below
3 rd - 2 nd	60 km/h & below
2 nd - 1 st	40 km/h & below



Notes.

Damage caused by incorrect Gear changing will not be covered by warranty.