

Instruments (Continued)



Coolant temperature gauge ()

When the coolant is over specified temperature, the 6th (H) segment flashes and high coolant temperature indicator lights. (P45)



If the 6th (H) segment flashes while riding: (P137)

If the coolant temperature gauge flashes sequentially or turns off: (P142)

Clock (12-hour display)

