

Competition Inspection

No	Item	Inspect For:	Action	Refer to Page:
13	swingarm bearings	smooth operation	replace	84
14	rear suspension linkage bushings	wear	replace	84
15	brake pads	wear beyond service limit	replace	89
16	drive chain: max. length/pin	25.1 in (637 mm) / 41 pins	replace	107
17	sprockets	wear and secure installation	replace or tighten	108
18	seat	security	tighten	—
19	control cables	smooth operation, kinks and correct routing	lubricate or replace	—
20	engine mounting bolts	tightness	tighten	—