


Electrical servicing



Wire harness inspection

Check for continuity of the Black/Blue wire between the fan motor relay 2P (Natural) connector and ECM 32P (Black) connector.

There should be continuity. If there is no continuity, repair or replace the wire harness.

Chapter lights / instruments / switches (2ED)

System location

