

(Ref. No.) Description	Function
(CB600F) (10) Odometer	Shows accumulated mileage.
(11) Tripmeter	Shows mileage per trip.
(12) Tripmeter reset knob	Resets tripmeter to zero (0). Turn knob in direction shown.
(CB600F II) (10) Odometer/Tripmeter display	Shows odometer and tripmeter.
Odometer	Shows accumulated mileage.
Tripmeter	Shows mileage trip.
(11) Odometer/Tripmeter select and reset button	Resets the tripmeter or select the operation mode: tripmeter and odometer (page 18).