

6. Inspect the front and rear sprocket teeth for excessive wear or damage. If necessary, have your Honda dealer replace a worn sprocket.



NOTICE

Use of a new chain with worn sprockets will cause rapid chain wear.



2. Turn the adjusting nuts (2) on the right and left chain adjusters an equal number of turns

to increase or decrease chain slack.

101