


# WIRING DIAGRAM



B	BLACK
BR	BROWN
BU	BLUE
BL	BLACK/BLUE
GR	GREEN
Y	YELLOW
OR	ORANGE
W	WHITE
GY	GRAY

COLOR COMB. GROUND MARKING

0030Z-HNO-A000

