

Ref. No.	Part No.	Description	Reqd. No. PC50	No. Used on		News No.
				From	To	
1	32983-044-010	GROMMET, wire cord .....	2	PC50-1000001	.....	
2	32100-063-000	HARNNESS, wire (Used in General) ...	1	PC50-1000001	.....	
	32100-063-620	HARNNESS, wire (Used in France) ...	1	PC50-1000001	.....	
	32100-063-690	HARNNESS, wire (Used in England) ...	1	PC50-1000001	.....	
3	30500-063-004	COIL, ignition .....	1	PC50-1000001	.....	
4	30700-063-681	CAP ASSY., noise suppresser .....	1	PC50-1000001	.....	
5	17911-023-000	GROMMET, throttle wire .....	1	PC50-1000001	.....	
6	50163-063-000	GROMMET, feed tube .....	1	PC50-1000001	.....	
7	50164-063-000	CAP, change cable hole .....	2	PC50-1000001	.....	
8	50162-063-000	GROMMET, screw hole .....	2	PC50-1000001	.....	
9	87125-253-680	PLATE A, name .....	1	PC50-1000001	.....	
10	87501-063-620	PLATE, registerd number .....	1	PC50-1000001	.....	
		(Used in France)				
11	50100-063-010D	BODY, frame (Columbia blue) .....	1	PC50-1000001	.....	
		(Used in General, England)				
	50100-063-010AW	BODY, frame (Bright red) .....	1	PC50-1000001	.....	
		(Used in General, England)				
	50100-063-010Z	BODY, frame (Non sanding) .....	1	PC50-1000001	.....	
		(Used in General, England)				
	50100-063-620D	BODY, frame (Columbia blue) .....	1	PC50-1000001	.....	
		(Used in France)				
	50100-063-620AW	BODY, frame (Bright red) .....	1	PC50-1000001	.....	
		(Used in France)				
	50100-063-620Z	BODY, frame (Non sanding) .....	1	PC50-1000001	.....	
		(Used in France)				
12	92000-08080-0A	BOLT, hex., 8x80 .....	1	.....	.....	
13	92000-08085-0A	BOLT, hex., 8x83 .....	1	.....	.....	
14	94001-08000-0S	NUT, hex., 8 mm .....	2	.....	.....	
15	94021-06020-0S	NUT, blind, 6 mm .....	1	.....	.....	
16	94111-06000	WASHER, spring, 6 mm .....	1	.....	.....	
17	94111-08000	WASHER, spring, 8 mm .....	2	.....	.....	