

## TORQUE VALUE

Cylinder bolt 50 N·m (5.0 kg-m, 36 ft-lb)

## TROUBLESHOOTING

### Low Compression

- Worn cylinder or piston rings

### Excessive Smoke

- Worn cylinder, piston, or piston rings
- Improper installation of piston rings
- Scored or scratched piston or cylinder wall

### Overheating

- Excessive carbon build-up on piston crown or combustion chamber

### Knocking or Abnormal Noise

- Worn piston and cylinder
- Excessive carbon build-up on piston crown or combustion chamber